


Annexure- A


List of the Work of Repair and Maintenance in Kendriya Vidyalaya NFR Maligaon

Ref: Advertisement published in Assam Tribune dated 08.12.2020

Sl No.	Name of the Work	Specification	Price Quoted (Including GST and Other taxes)
1	<p>a) Fixing of new , strong iron Gates with elegant finishing with iron sheet for safety of students at the 1<sup>st</sup> entry point of school campus.</p> <p>b) Raising the height of existing Iron Gate by 1 ft and putting iron Cover Sheet with names of School written in Iron design</p> <p>c) Fixing of new , strong iron Gates with elegant finishing with iron sheet for safety of students at the 2<sup>nd</sup> entry point of school campus.</p>	<p>a) <u>Gate</u>-Length-6.73 meter, Height-5.9 meter <u>Grill</u>- Length-5 meter, Height-2.5 meter, Thickness of Iron- 2.5 inch</p> <p>b) Length- 5 meter, Height-2.5 meter</p> <p>c) <u>Gate</u>:- Length- 3.63 meter Height-2.0 meter, Iron Thickness- 2.5 inch</p>	
2	Writing of school name with stainless steel on newly constructed main gate.	Length-6.73 meter, Width-0.7 meter	
3	Construction of an RCC gate at 2 <sup>nd</sup> entry point of School Campus	<u>Gate</u> :- Length- 5.3 meter Height-1.65 meter	
4	Steel name boards/plates for all class rooms, labs, departments etc. with fixing.(Per Piece)	Length – 12 inch Width - 6 inch	
5	Cobra fencing on boundary wall.	Length -110.5 meter, Height- 2 ft	
6	Painting of boundary wall ( weather paint) with Asian paints.	Length:- 110.5 meter, Height:- 2 meter	
7	Aluminum grilled counter with glass fitting inside at security room for visitors with glass fittings inside	Length- 3 ft Height- 2 ft	
8	<p>a) Repair of cemented drains and painting of side platform wall above drains outside school building.</p> <p>b) Repair of side floor beside drain with cement plastering</p>	<p>a) <u>Drains at Right Side of Entrance of School Building</u>:- Length- 82 meter, Height- 2 ft <u>Drains at Left Side of Entrance of School Building</u>:- Length- 78.3 meter, Height- 2 ft;</p> <p>b) Length- 160.3 m, width- 4.5 ft</p>	
9	Repair and painting of Small boundary wall and small platform nearby play grounds, front drains and nearby children park;	<p><u>Near by Play Ground</u>: Length-188.3 meter , Height – 1 ft, Width- 1 ft <u>Near by Drain</u>: Length- 86.4 meter, Height 2 ft 2 inch <u>Near by Children Park</u>: Length-63 meter, Height- 1 ft, Width- 1 ft</p>	
10	Installation of aluminum grilled counter in office.	Length- 15 ft 3 inch, Height - 4 ft	

  
08/12/2020  
Principal  
Kendriya Vidyalaya  
NFR Maligaon, Nalbari

11	Tiling of stairs with Kajaria Tiles.	Length – 24.7 meter, width-1.6 meter	
12	Demolition of old cemented stage at Assembly ground and leveling the ground with cemented concrete flooring.	Length – 8.9 meter , width – 7.5 meter , Height – 2 ft 8 inch	
13	<p>a) Repairing of the fountain wall increasing the brick wall height by 1 ft and putting weather coat painting.</p> <p>b) Installing stainless steel fencing around the Fountain with elegant look at the entry of school building.</p>	<p>a) <u>Circumference of Fountain</u> 23 meter, Existing wall Height- 2 ft</p> <p>b) <u>Circumference of Fountain</u> 23 meter, <u>Height of Steel Fencing</u>- 1 meter</p>	
14	Removal of old iron grills and fixing of new steel grills with good designs at entry point of School building.	Length – 3 meter , Height – 2.3 meter	
15	<p>Renovation and repairing of Principal and Vice Principal chamber with interior decoration.</p> <p>*Changing of Existing Floor Tiles &amp; Wall Tiles of minimum 2 ft by 2 ft of Kajaria Brand.</p> <p>* Making Provision of an Aluminum Window in Principal's Chamber with Aluminum Grill and Slider</p> <p>* Changing of the door of Principal's Chamber with Aluminum Glass door outside and good quality wooden inside door of burnished teak wood of required thickness.</p> <p>* Wall Painting in Principal and Vice Principal's Room</p>	<p><b>Principal's Room:</b> Length – 20 ft 3 inch , width – 15 ft 4 inch.</p> <p><b>Wall Height for tiles fixing-</b> Length – 20 ft 3 inch , width – 15 ft 4 inch, Height- 3 ft.</p> <p><b>Vice Principal's Room:</b> Length – 10 ft 8 inch, width – 14 ft.</p> <p><b>Aluminum Window of Principal's Chamber:-</b> Length- 3 ft, Width- 5 ft</p> <p><b>Door of Principal's Room-</b> Door Height -6 ft 8 inch, width- 4 ft</p>	
16	Painting of walls of Games Room	Length: 27.8 meter, Height- 12.6 meter	
17	<p>a) Repair &amp; painting of Backside wall of Primary Resource Room</p> <p>b) Repair of wall with cement plastering and painting</p>	<p>a) Length:- 9 meter, Height- 2 meter</p> <p>b) Wherever required (Rates to be quoted for per meter)</p>	
18	Tata Durashine Colored Roof Sheet over RO Water Plant with Iron poles and 3 ft brick wall with cement plastering and painting on all sides.	Length- 6 meter, Width- 3 meter, Height- 2 meter.	
19	Repair of front boundary wall (Right Side of school Building). Brick wall with cement plastering and painting.	Length- 6 meter, Height- 5 ft	
20	Painting of Tree Trunks with good quality weather painting	Height- 4 ft, Total Nos. 60 Trees Approximately	
21	<p>a) Repairing of wooden Side Panel of Ply board make</p> <p>b) Repair of Computer Table in secondary resource room of Ply board make.</p>	<p>a) 1 Side Panel:- Length- 5 ft 6 inch, Height- 5 ft</p> <p>b) Computer Table: Total Length- 40 ft, Width- 1 ft 5 inch, Height- 2 ft 9 inch</p>	
22	Making of a Glow Sign Board with School Name, written in Hindi, English and Assamese with fitting charges in the second floor of the School building towards Kamakhya Station Side.	Length- 20 ft, Height- 5 ft	

  
 08/12/2022  
 Kendriya Vidyalaya  
 কলকাতা বিদ্যালয়, মালগাঁও  
 Malgaon